


# RAC Mechanical Check



PJ16WJO

VOLKSWAGEN

CRAFTER CR35 TDI -  
1968cc

42,298 miles

Engine	
Alternator Drive-Belt shows no visible signs of damage	✓
Coolant Level OK	✓
Engine Oil OK	✓
Engine starts	✓
Engine not smoking	✓
Engine runs smoothly	✓
Engine not unduly noisy	✓
Exhaust System not blowing	✓
No excessive motor fumes from the engine	✓

Engine Comments

Transmission	
Automatic transmission functional	NA
Clutch functional	✓
Engage gears	✓
Engage reverse gear	✓

Transmission Comments

Steering	
No excessive play at the steering wheel	✓
No undue suspension wear/leaks	✗
Power Steering operational	✓

Steering Comment  
steering wheel shaking when driving.

Brakes	
Brake Fluid level OK	✓
Brake Pedal pressure	✓
Handbrake holds with clutch biting	✓

Brakes Comment

Windscreen	
Washers OK	✓
Windscreen meets MOT standard	✓
Wipers OK	✓

Windscreen Comments

Lights	
Front fog-lights (if fitted) function correctly	NA
Front headlights function correctly	✓
Indicators function correctly	✓
Rear brakes lights function correctly	✓
Rear fog-lights function correctly	✓
Rear lights function correctly	✓

Lights Comments

Interior	
ABS Warning Light not illuminated	✓
Air Con/Climate Control operates satisfactorily	NA
Airbag Light not illuminated	✓
All electric windows function correctly	✓
Brake-Light Warning Light not illuminated	✓
EML Light not illuminated	✓
Electric sunroof functions (if fitted)	NA
Electric convertible-roof functions correctly (If Applicable)	NA
Engine Oil Warning Light not illuminated	✓
Entertainment System turns on and functions	✓
Heater blows hot (excludes temp calibration)	✓
Sat Nav fitted	✓
Seat Belt condition satisfactory	✓
Seat Belts function	✓
Service/Message Light not illuminated	✓
Vehicle's Horn functions correctly	✓

Interior Comments  
no satnav sim.

General Comments

RAC Road Test Distance			
Miles Tested:	3	Minutes Tested:	10

RAC Tester Name  
Print Name: R Garrod

Date  
01/05/2019